

## Inspection Photos

Location Name: LARAMIE ENERGY LLC My Way Ranch /18-5 Pad

Location ID: 334552



Network: Jan 16, 2020 at 1:07:09 PM MS  
Local: Jan 16, 2020 at 1:07:09 PM MS  
+39.1913, -107.929

Photo #0424 photo from entrance to location.



Network: Jan 16, 2020 at 1:11:32 PM MS  
Local: Jan 16, 2020 at 1:11:32 PM MS  
+39.1915, -107.930

Photo #0425 Multiple holes in tank containment liner.

## Inspection Photos

Location Name: LARAMIE ENERGY LLC My Way Ranch /18-5 Pad

Location ID: 334552



**Photo #0429 Multiple holes in tank containment liner.**