

Inspection Photos

Location Name: LARAMIE ENERGY LLC Campbell /18-12 Pad

Location ID: 334515



Photo #0430 photo from entrance to location.



Photo #0431 Hole in tank containment liner.