

Inspection Photos

Loc#334653

Operator: Caerus

Inspection Number: 692401810

Inspection Date: 1/10/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Interim area to West.

January 10,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Clem Jr Loc#334653



Photo#2:
View of Interim Area.



Photo#3:
View of Interim Area and rock retaining wall.

January 10,2020



Photo#4:
View of Subsidence area North of Separators from
12/20/19 Insp.

January 10,2020



Photo#5:
View of Subsidence area North of Separators
from 1/10/20 Insp.



Photo#6:
Work in progress at spill area.



Photo#7:
Drip areas at Wellheads.

January 10,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Clem Jr Loc#334653