

## Inspection Photos

Location Name: RADISH 44-8 CA DATE 2-16-20

API#: 05-071-09376

INSP. #: 695102052



Colorado Oil & Gas Conservation Commission  
37.18748, -104.91007, 256°  
2020/01/16 14:08:39

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission  
37.26618, -104.90487, 2445.0m, 327°  
2020/01/16 14:09:58

PHOTO 2: WELL SIGN

## Inspection Photos

Location Name: RADISH 44-8 CA DATE 2-16-20

API#: 05-071-09376

INSP. #: 695102052



**PHOTO 3: AREA OF IMPACTED SOIL NEAR WELLHEAD  
APPEARS TO BE COMING FROM DRIVEHEAD. Non E&P Waste  
not properly stored, handled, transported, treated, or  
disposed per Rule 907A. CA DATE 2-16-20**