

Inspection Photos
Operator: BP America
Location/API #: 067-09469
Date: 1-15-2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Although snow covered, revegetation appears to be progressing with rubber rabbitbrush and sand dropseed.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area, comprised of open pinyon and juniper woodland with sagebrush dominated understory.