

Inspection Photos
Location Name: Ellis 13-29
Location ID: 313325



Photo 1. Photo of access road not maintained for winter access.

