

Inspection Photos  
Operator: BP America  
Location/API #: 067-09449  
Date: 1-15-2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is comprised of grasses and shrubs such as rubber rabbitbrush and crested wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area, comprised of open pinyon and juniper woodland with sagebrush dominated understory.