

**Inspection Photos**  
**Location Name: Ehler-61S67W/4SESE**  
**Location Number: 320460**



**Photo 1: Location sign**



**Photo 2: Tracking pad at gate in the perimeter fence.**



**Inspection Photos**  
**Location Name: Ehler-61S67W/4SESE**  
**Location Number: 320460**



**Photo 3: Wetland to the north of the perimeter fence. Some of the 16 temporary piezometers (vertical narrow white PVC pipes) are visible.**



**Photo 4: Repairs to portion of the perimeter fence that blew down.**

**Inspection Photos**  
**Location Name: Ehler-61S67W/4SESE**  
**Location Number: 320460**



**Photo 5: Portion of the open excavation being infiltrated by ground water.**

**Photo 6: Portion of the open excavation being infiltrated by ground water.**