

Inspection Photos

API: 05-017-07439

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 1/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07439 | Date: 1/14/2020

Inspection Photos



Photo 2. Center of the location facing north. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07439 | Date: 1/14/2020

Inspection Photos



Photo 3. Center of the location facing west. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07439 | Date: 1/14/2020

Inspection Photos



Photo 4. Center of the location facing south. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07439 | Date: 1/14/2020

Inspection Photos



Photo 4. Center of the location facing east. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07439 | Date: 1/14/2020