

Levison 33X
API: 05-103-07521
Inspection: 679707035



Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Levison 33X
API: 05-103-07521
Inspection: 679707035



Photo 2. NW corner of location without berm.

