

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/16/2020

Submitted Date:

01/17/2020

Document Number:

697000403

**FIELD INSPECTION FORM**

Loc ID 321618 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10713  
Name of Operator: DARRAH OIL COMPANY LLC  
Address: 125 N MARKET STE 1425  
City: WICHITA State: KS Zip: 67202

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone          | Email                        | Comment |
|-----------------|----------------|------------------------------|---------|
| Atterbury, Mike | (316) 219-3390 | mike.atterbury@darrahoil.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 207534      | WELL | PR     | 12/07/1984  | OW         | 017-06469 | LOWE-ARNOLD 4 | PR          |

**General Comment:**

[Routine Inspection](#)

**Location**

|                    |                                 |       |  |
|--------------------|---------------------------------|-------|--|
| <b>Lease Road:</b> |                                 |       |  |
| Type               | Access                          |       |  |
| comment:           | Gravel road through farm ground |       |  |
| Corrective Action: |                                 | Date: |  |

Overall Good:

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Stickers on tanks    |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Lease sign by tanks  |       |  |
| Corrective Action:   |                      | Date: |  |

|                           |  |             |
|---------------------------|--|-------------|
| Emergency Contact Number: |  |             |
| Comment:                  | <input style="width: 500px; height: 20px;" type="text"/> |             |
| Corrective Action:        | <input style="width: 500px; height: 20px;" type="text"/> | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                                 |  |       |                 |
|---------------------------------|--|-------|-----------------|
| <b>Equipment:</b>               |  |       | corrective date |
| Type: Horizontal Heater Treater | # 1  |       |                 |
| Comment:                        | Treater next to FWKO   |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Ancillary equipment       | # 2  |       |                 |
| Comment:                        | Electric panel and cathodic rectifier                          |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Horizontal Separator      | # 1  |       |                 |
| Comment:                        | Unidralic separator skid on east side of wellhead (Not in use) |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: FWKO                      | # 1  |       |                 |
| Comment:                        |  |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Pump Jack                 | # 1  |       |                 |
| Comment:                        | American 320   |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Prime Mover               | # 1  |       |                 |

|   |  |       |
|---|--|-------|
| Comment: <a href="#">Electric motor</a> |  |       |
| Corrective Action:                      |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 4 | 300 BBLs | STEEL AST |         | 38.720580,-102.519600 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 207534 Type: WELL API Number: 017-06469 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central tank battery for \(Lowe-Arnold 4 & 5\)](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT