

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/16/2020

Submitted Date:

01/16/2020

Document Number:

699500771**FIELD INSPECTION FORM**
 Loc ID 460290 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460417	WELL	DG	02/27/2019		123-49356	RANGER 7-19HZ	WO
460418	WELL	DG	02/28/2019		123-49357	RANGER 7-20HZ	WO
460419	WELL	DG	02/17/2019		123-49358	RANGER 7-6HZ	WO
460420	WELL	DG	02/14/2019		123-49359	RANGER 7-2HZ	WO
460421	WELL	DG	02/17/2019		123-49360	RANGER 7-7HZ	WO
460422	WELL	DG	02/20/2019		123-49361	RANGER 7-10HZ	WO
460423	WELL	DG	02/23/2019		123-49362	RANGER 7-14HZ	WO
460424	WELL	DG	02/19/2019		123-49363	RANGER 7-9HZ	WO
460425	WELL	DG	02/18/2019		123-49364	RANGER 7-8HZ	WO
460426	WELL	DG	02/21/2019		123-49365	RANGER 7-11HZ	WO
460427	WELL	DG	02/22/2019		123-49366	RANGER 7-13HZ	WO
460428	WELL	DG	02/13/2019		123-49367	RANGER 7-1HZ	WO
460429	WELL	DG	02/24/2019		123-49368	RANGER 7-16HZ	WO
460430	WELL	DG	02/24/2019		123-49369	RANGER 7-15HZ	WO
460431	WELL	DG	02/15/2019		123-49370	RANGER 7-4HZ	WO
460432	WELL	DG	02/21/2019		123-49371	RANGER 7-12HZ	WO
460433	WELL	DG	02/26/2019		123-49372	RANGER 7-18HZ	WO
460434	WELL	DG	02/16/2019		123-49373	RANGER 7-5HZ	WO
460435	WELL	DG	02/25/2019		123-49374	RANGER 7-17HZ	WO
460436	WELL	DG	02/14/2019		123-49375	RANGER 7-3HZ	WO

**General Comment:**

--

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>460417</u>	Type: <u>WELL</u>	API Number: <u>123-49356</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460418</u>	Type: <u>WELL</u>	API Number: <u>123-49357</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460419</u>	Type: <u>WELL</u>	API Number: <u>123-49358</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460420</u>	Type: <u>WELL</u>	API Number: <u>123-49359</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460421</u>	Type: <u>WELL</u>	API Number: <u>123-49360</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460422</u>	Type: <u>WELL</u>	API Number: <u>123-49361</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460423</u>	Type: <u>WELL</u>	API Number: <u>123-49362</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460424</u>	Type: <u>WELL</u>	API Number: <u>123-49363</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460425</u>	Type: <u>WELL</u>	API Number: <u>123-49364</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460426</u>	Type: <u>WELL</u>	API Number: <u>123-49365</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460427</u>	Type: <u>WELL</u>	API Number: <u>123-49366</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460428</u>	Type: <u>WELL</u>	API Number: <u>123-49367</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460429</u>	Type: <u>WELL</u>	API Number: <u>123-49368</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460430</u>	Type: <u>WELL</u>	API Number: <u>123-49369</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460431</u>	Type: <u>WELL</u>	API Number: <u>123-49370</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460432</u>	Type: <u>WELL</u>	API Number: <u>123-49371</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460433</u>	Type: <u>WELL</u>	API Number: <u>123-49372</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460434</u>	Type: <u>WELL</u>	API Number: <u>123-49373</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>460435</u>	Type: <u>WELL</u>	API Number: <u>123-49374</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>

Facility ID:	460436	Type:	WELL	API Number:	123-49375	Status:	DG	Insp. Status:	WO
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Pass	Ditches	Pass			
Rip Rap	Pass					
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	01/16/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500772	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5041611">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5041611</a>