



## Final Reclamation Inspection Form

Site: PHIL 1-6  
 Date: 12/26/2019 Inspector: Trevor Hartwig  
 Conditions: 36 and windy

Land Use: Pasture Access Road in Use: Yes  
 If Crop: \_\_\_\_\_ If yes, in use by: Landowner  
 If other land use: No Located on active pad? No  
 Located in interim rec of active pad? No

TB inspected: NA TB status: Reclaimed  
 TB name and/or #: \_\_\_\_\_

	Present (Y/N)	Notes
Debris or Trash on Site	No	
Equipment on Site (culverts, pipes, etc.)	No	
Livestock Grazing/Disturbances	No	
Vehicle Disturbances	No	
Wildlife Disturbances	No	
Seed Germination	Yes	
Plants Vigorous	Yes	
Uniform growth (height and density)	Yes	
Undesirable Species (non-noxious weeds)	Yes	
Noxious Weeds	No	
Stormwater Issues (erosion)	No	
Subsidence (depressions, sinking)	No	
Site Re-contoured Properly	Yes	
Road Re-contoured Properly	Yes	
Road base/gravel on site (road or pad)	No	
Compaction (On-Site)	NA	1 in @ 300 psi
Compaction (Off-Site)	NA	1 in @ 300 psi
Reclamation area fenced	No	

Plants Observed	On Site	Off Site	Desirable
blue grama	Yes	Yes	Yes
Sand drop seed	Yes	Yes	Yes
Curly dock	Yes	Yes	No
Prickly pear	Yes	Yes	Yes
			NA

Recommendations:	
Seeding	No
Weed Control	No
Erosion Control	No
Compaction Alleviation	No
Other:	

Other Comments/Observations: Large parts of the surrounding property contain curly dock. Recommend LPI in the spring/early summer when plants are growing again

Recommended for Final Form 4? Yes



## PHOTOGRAPHIC LOG



**Photograph 1:** North facing photograph.



**Photograph 2:** East facing photograph.



**Photograph 3:** South facing photograph.



**Photograph 4:** West facing photograph.

## PHOTOGRAPHIC LOG



**Photograph 5:** Overview photograph.