

Inspection Photos

Loc#336015

Operator: Ursa

Inspection Number: 692401821

Inspection Date: 1/17/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

January 17,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Robinson Loc#336015



Photo#2:
View of Interim Reclamation area at West side of Location.

January 17,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Robinson Loc#336015



Photo#3:
Well at North end of Well lineup. Arrow indicates vibrating panel.



Photo#4:
Panels at Northwest corner of Well corral. Arrow indicates vibrating panel.

January 17, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Robinson Loc#336015