

Inspection Photos
Location Name: Schmidt K25-18
Location ID: 302808



Debris on 1/6/2020



Debris on 1/21/2020