

Final Reclamation Inspection

January 8, 2020

Operator: BATES* JAMES EDWARD - 6575

API #: 05-005-06064

Inspection Document #: 697501042

Arapahoe County, CO

SWSW Section 14 T4S R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PRICE #1
API #: 05-001-06796



Photo 1. COGCC GISOnline aerial imagery from 2009 during active operations. Imagery illustrates the location of the well and the offsite tank battery.

Inspection Photos
Location Name: PRICE #1
API #: 05-001-06796



Photo 2. Zoomed in photo of the tank battery location. Photo illustrates the total disturbance including a produced water pit spill.

Inspection Photos
Location Name: PRICE #1
API #: 05-001-06796



Photo 3. Photo taken from a well location, facing East. Photo illustrates an approximate 30' x 30' area does not meet Rule 1004 vegetative standards. Operator stated he never seeded the well location.

Inspection Photos
Location Name: PRICE #1
API #: 05-001-06796



Photo 4. Photo taken from the northern tank battery, facing North. Photo illustrates minimal to no vegetative growth. Note: minimal to no vegetative growth was observed throughout any portion of the tank battery location. Operator stated he never seeded the tank battery location.

Inspection Photos
Location Name: PRICE #1
API #: 05-001-06796



Photo 5. Photo taken from the northern tank battery, facing East. See comments under Photo 4.

Inspection Photos
Location Name: PRICE #1
API #: 05-001-06796



Photo 6. Photo taken from the southern tank battery, facing South. Erosion occurring along the southern tank battery and along portions of the produced water spill.

Inspection Photos
Location Name: PRICE #1
API #: 05-001-06796



Photo 7. Photo taken from the southern tank battery, facing South. Photo illustrates erosion occurring along portions of the produced water spill.

Inspection Photos
Location Name: PRICE #1
API #: 05-001-06796



Photo 8. Tank battery reference photo taken northwest of the tank battery, facing West. Photo illustrates blue grama as the dominant vegetative cover.