

## Inspection Photos

Location Name: SKURICH/ROTHE-65N63W /6SE

Location #: 331446



**Photo #1**

**Skurich/Rothe 6A (05-123-20697) Wellsite**

**Plugged & Abandoned | PA**

*~ 30 yds.*

*Reclamation progressing*



**Photo #2**

**Skurich/Rothe 6A Battery site**

**Abandoned: *ALL Equipment removed***

*Reclamation progressing*