

Inspection Photos

Location Name: SKURICH ROTH-65N63W /6SENE

Location #: 330616



Colorado Oil & Gas Conservation Commission
40.43023, -104.47246, 1413.0m, 313°
01/21/2020 04:10:48 PM

Photo #1

Skurich Roth 42-6 (05-123-19362) Wellsite

Plugged & Abandoned | PA

~ 25 yds.

Reclamation progressing



Colorado Oil & Gas Conservation Commission
40.43053, -104.47686, 1404.0m, 236°
01/21/2020 04:18:26 PM

Photo #2

Skurich Roth 42-6 Battery site

Abandoned: ALL Equipment removed

Reclamation progressing