

Inspection Photos
Location Name: Strear 1-15A
Location ID: 331569



Photo 1 WH sign




Photo 2 WH

Inspection Photos
Location Name: Strear 1-15A
Location ID: 331569



Photo 3 TB sign



Photo 4 TB

Inspection Photos
Location Name: Strear 1-15A
Location ID: 331569



Photo 5 ECDs, Gas Meter Run & Horiz. Heated Separator



Photo 6 Horiz. Heated Separator

Inspection Photos
Location Name: Strear 1-15A
Location ID: 331569



Photo 7 Gas meter Runs Stained soil under flow line



Photo 8 Stained soil by Gas meter run flow line