

Interim Reclamation and Stormwater Inspection

January 10, 2020

Operator: HIGHPOINT OPERATING CORPORATION- #10071

Location ID: 458768

Inspection Document #: 697501048

Weld County, CO

NWSW Section 4 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Wetco /4-63-4 SW
Location ID: 458768



Photo 1. Photo taken from the southeastern interim area, facing Northwest. Photo illustrates Operator has performed interim reclamation to reduce all areas only needed for production operations.

Photo also illustrates germination within the interim area. A follow up vegetative inspection will be conducted at a future date.

Inspection Photos
Location Name: Wetco /4-63-4 SW
Location ID: 458768




Photo 2. Photo taken from the southeastern interim area, facing West. See comments under Photo 1.

Photo also illustrates the stored topsoil along the southern location to facilitate final reclamation activities.

Inspection Photos
Location Name: Wetco /4-63-4 SW
Location ID: 458768



Photo 3. Photo taken from the southeastern interim area, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Wetco /4-63-4 SW
Location ID: 458768



Photo 4. Photo taken from the southeastern interim area, facing Southeast.
See comments under Photo 1.

