

Inspection Photos

Loc#336038

Operator: Ursa

Inspection Number: 692401827

Inspection Date: 1/17/20





Photo#2:
Escape board needing adjustment.



Photo#3:
Open rat hole(?) between PR Wells.

January 17, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa River Ranch B Loc#336038



Photo#4:
Interim Reclamation area. Insert of weedy portion on Pad perimeter.

January 17,2020



Photo#5:
Interim Reclamation area and Invasive Russian Olive.

January 17,2020