

# Inspection Photos

API: 05-121-11030

Operator: ST CROIX OPERATING

Inspection Date: 1/15/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-121-11030 | Date: 1/15/2020

## Inspection Photos



**Photo 1.** Facing west along the former access road.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 05-121-11030 | Date: 1/15/2020



## Inspection Photos



**Photo 2.** Center of the location facing west.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 05-121-11030 | Date: 1/15/2020



## Inspection Photos



**Photo 3.** Center of the location facing north.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 05-121-11030 | Date: 1/15/2020



## Inspection Photos



**Photo 4.** Center of the location facing east.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 05-121-11030 | Date: 1/15/2020



## Inspection Photos



**Photo 5.** Center of the location facing south.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 05-121-11030 | Date: 1/15/2020



## Inspection Photos




**Photo 6.** View of groundcover shows predominately undesirable weeds at the location.





## Inspection Photos



**Photo 7.** Facing northwest at the beginning of transect at the disturbed location. Vegetation at the location is predominately weed cover consisting of Kochia and Russian thistle.



**Photo 8.** Ground cover at midpoint along the transect at the disturbed location. Vegetation at the location is predominately weed cover consisting of Kochia and Russian thistle.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-121-11030 | Date: 1/15/2020



## Inspection Photos



**Photo 9.** Facing southwest along the transect at the disturbed location. Vegetation at the location is predominately weed cover consisting of Kochia and Russian thistle.



**Photo 10.** Facing northeast along the transect at the disturbed location. Vegetation at the location is predominately weed cover consisting of Kochia and Russian thistle.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources


API: 05-121-11030 | Date: 1/15/2020



## Inspection Photos



**Photo 11.** Facing southeast at the end of the transect at the disturbed location. Vegetation at the location is predominately weed cover consisting of Kochia and Russian thistle.



**Photo 12.** Facing northwest at the beginning of the transect at the undisturbed reference site. Vegetation in the undisturbed reference is CRP grassland consisting of Sideoats grama and Sand dropseed.





## Inspection Photos



**Photo 13.** Ground cover at midpoint along the transect at the undisturbed reference site. Vegetation in the undisturbed reference is CRP grassland consisting of Sideoats grama and Sand dropseed.



**Photo 14.** Facing southwest along the transect at the undisturbed reference site. Vegetation in the undisturbed reference is CRP grassland consisting of Sideoats grama and Sand dropseed.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-121-11030 | Date: 1/15/2020



## Inspection Photos



**Photo 15.** Facing northeast along the transect at the undisturbed reference site. Vegetation in the undisturbed reference is CRP grassland consisting of Sideoats grama and Sand dropseed.



**Photo 16.** Facing southeast at the end of the transect at the undisturbed reference site. Vegetation in the undisturbed reference is CRP grassland consisting of Sideoats grama and Sand dropseed.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-121-11030 | Date: 1/15/2020



## Cover Data

Date: 1/15/2020 Inspected By: Rya-Costin + Stephen

Location/Operator: API #121-11030 St. Croix

[illegible]

2nd= second hit; P= plant species present but not hit