

Inspection Photos

API: 05-071-07546

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/22/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 1/22/2019

Inspection Photos



Photo 1. The area of erosion has been repaired along the main road. A channel has been installed across the road at this point. It is a concern that if not maintained the low area may create water pooling in the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 1/22/2019

Inspection Photos



Photo 2. The area of erosion identified along the access road has been repaired. Rock rip/rap was installed and the cut slope is seeded and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 1/22/2019

Inspection Photos



Photo 3. Facing north at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 1/22/2019

Inspection Photos



Photo 4. The south side of the location has been regraded, seeded, and hydromulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07546 | Date: 1/22/2019