

# Interim Reclamation and Stormwater Inspection

January 16, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 457013

Inspection Document #: 697501056

Weld County, CO

SWNW Section 21 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: REESE /22-21HZ  
Location ID: 457013



**Photo 1.** Photo taken from the southeastern location, facing Northwest. Photo illustrates Operator has performed Interim Reclamation activities to reduce all areas only needed for production operations.

Inspection Photos  
Location Name: REESE /22-21HZ  
Location ID: 457013



**Photo 2.** Photo taken from the southeastern location, facing West. See comments under Photo 1. Red-dashed line is the well location.

Note: Operator has removed all construction stormwater BMPs from the location after performing interim reclamation.

Inspection Photos  
Location Name: REESE /22-21HZ  
Location ID: 457013



01.16.2020 14:14

**Photo 3.** Photo taken from the southwestern well location, facing Southwest. See comments under Photo 1 and 2.

Inspection Photos  
Location Name: REESE /22-21HZ  
Location ID: 457013



**Photo 4.** Photo taken from the southwestern well location, facing North. See comments under Photo 1 and 2.