

Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



Photo #0445 from SW corner of location



Photo #0446 Not all holes patched in tank containment liner.

Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



Photo #0447 Not all holes patched in tank containment liner.



Photo #0448 Not all holes patched in tank containment liner.