

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 1 – Location Sign



Photo 2 – 6" pipe where 90 broke

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Colorado Oil and Gas Conservation Commission
40.80926, -103.83178, 4672.9ft, 207°
01/22/2020 13:24:27

Photo 3 – Looking South



Colorado Oil and Gas Conservation Commission
40.80917, -103.83171, 4673.2ft, 284°
01/22/2020 13:23:23

Photo 4 – Looking west towards tanks

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Colorado Oil and Gas Conservation Commission
40.80926, -103.83175, 4669.5ft, 22°
01/22/2020 13:24:33

Photo 5 – Looking North



Colorado Oil and Gas Conservation Commission
40.80891, -103.83161, 4625.4ft, 202°
01/22/2020 13:27:01

Photo 6 – Looking South

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 7 – Looking West at ditch



Photo 8 – Looking East

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 9 – Looking West at ditch



Photo 10 – Looking East at Retention Pond

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 11 – Looking East at Retention Pond



Photo 12 – Looking East at Retention Pond