

Inspection Photos
Location Name: Rohn PC LD 04-03
Location ID: 423807



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: Rohn PC LD 04-03
Location ID: 423807



Colorado Oil and Gas Conservation Commission
40.78593, -103.8715, 4649.9ft, 209°
01/16/2020 13:49:22

Photo 3 – Unused Methanol Tank/Containment