

Inspection Photos

Location Name: STATE 5519-65N63W /8SWSE

Location #: 330952



Colorado Oil & Gas Conservation Commission
40.40798, -104.4584, 1428.0m, 177°
01/22/2020 04:21:48 PM

Photo #1

State 5519 8-34 (05-123-19925) Wellsite
Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
40.4104, -104.45606, 1428.0m, 110°
01/22/2020 04:39:01 PM

Photo #2

State 5519 8-43, 8-34 Battery site
Inactive | Shut-down
*Battery formerly served 3 other wells .
(State 5519 33-8, 44-8, 8A)
Plugged & Abandoned | PA*