

Inspection Photos

Location Name: GOLDEN EAGLE 30-14 2-22-20

API#: 05-071-08650

INSP. #: 695102086



Colorado Oil & Gas Conservation Commission
37.13724, -104.93152, 2244.0m, 192°
2020/01/22 14:57:54

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.13654, -104.93193, 2266.0m, 262°
2020/01/22 14:58:46

PHOTO 2: WELL SIGN



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: GOLDEN EAGLE 30-14 CA DATE 2-23-20

API#: 05-071-08650

INSP. #: 695102086



Colorado Oil & Gas Conservation Commission
37.13658, -104.93199, 2273.0m, 316°
2020/01/22 15:11:17



Colorado Oil & Gas Conservation Commission
37.13654, -104.93194, 2267.0m, 280°
2020/01/22 14:58:52

PHOTO 3: MECHANICAL CONDITION. **CLEAN COMPRESSOR AND REPAIR LEAKS (TO PREVENT FUTURE CONTAMINATION)**, Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 2-23-20.

PHOTO 4: AREA OF IMPACTED SOIL NEAR LOWEST POINT OF COMPRESSOR SKID. **Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 1-28-20**

Inspection Photos

Location Name: GOLDEN EAGLE 30-14 CA DATE 2-22-20

API#: 05-071-08650

INSP. #: 695102086



Colorado Oil & Gas Conservation Commission
37.13655, -104.93193, 2268.0m, 326°
2020/01/22 14:59:02



Colorado Oil & Gas Conservation Commission
37.13654, -104.93194, 2267.0m, 280°
2020/01/22 14:58:52

PHOTO 5: COMPRESSOR SKID IS FULL OF OILY WATER AND IT IS LEAKING ON THE LOCATION CONTAMINATING THE SOIL AND POTENTIALLY MIXING WITH STORM WATER. **Comply with general provisions of the oil and gas act for wildlife protection. 1-28-20**

PHOTO 4: AREA OF IMPACTED SOIL NEAR LOWEST POINT OF COMPRESSOR SKID. **Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. CA DATE 1-28-20**