

Letter Bob Gilbert Landowner



WELL SITE INSPECTION FORM

WELL NAME Gilbert Lee #2
OPERATOR Frontier O&G
LOCATION NW 5W 30-33-56W
FIELD _____

API NUMBER 05 - 121 - 09948
PERMIT NUMBER _____
COUNTY Washington
INSPECTOR Bin Rley

AL/PA/DA INSPECTION RESULTS:

PASS(Y) 1 FAIL(N) DATE 10-5-88 WELL STATUS: FN _____ FD _____ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: 8-6-83 DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES NO _____ PITS BACKFILLED: YES _____ NO
MATERIAL BURIED: YES NO _____ NA _____ SITE CLEAN: YES NO _____
BOND RELEASE OK: YES _____ NO FED _____ HOLE MARKER: YES _____ NO

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS drill pits open

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET
DENVER, COLORADO 80203

WILLIAM R. SMITH
Director
DENNIS R. BICKNELL
Deputy Director

(303) 894-2100

ROY ROMER
Governor

October 14, 1988

Frontier Oil & Gas
3 East Henderson Street
Cleburne, Texas 76031

Re: Gilbert Lee #2
API #05-121-09948
NWSW 30-3S-56W
Washington County, Colorado

Dear Sir,


The above captioned well has been plugged. However an on-site inspection on October 6, 1988 revealed that additional material and equipment must be removed and final leveling of the site completed prior to approval for site abandonment. If applicable anchors should be removed and risers cut off 3' below G.L.

Please notify this office in writing when all abandonment work is completed. Oil and Gas Conservation Rule 317 and 319 require locations to be restored within a reasonable time, not to exceed six (6) months, to their original conditions.

It is recommended the restoration be completed at the earliest convenience with mutual agreement of the operator and land owner.

Please feel free to contact this office if there are further questions.

Sincerely,



Eddie B. Binkley,
Petroleum Engineer

EBB/pah
0032I