

Inspection Photos

API: 05-043-40027

Operator: CINNAMON CREEK OIL & GAS

Inspection Date: 1/23/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40027 | Date: 1/23/2020

Inspection Photos



Photo 1. Facing west along the access road. The road has been repaired and road base has been spread along the road and is now compacted and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40027 | Date: 1/23/2020

Inspection Photos



Photo 2. Facing west further along the road. Road has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40027 | Date: 1/23/2020

Inspection Photos



Photo 3. Facing toward the location. Rig is onsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40027 | Date: 1/23/2020