

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 1: Wellhead Sign




Photo 2: Wellhead



Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 3: Stained soil removed



Photo 4: Wellhead Sign



Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 5: Wellhead



Photo 6: Stained soil removed

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 7: Wellhead Sign



Photo 8: Wellhead



Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Colorado Oil and Gas Conservation Commission
40.46495, -104.84122, 1424.1m, 3°
Jan 23, 2020 09:51:45

Photo 9: Stained soil



Colorado Oil and Gas Conservation Commission
40.46495, -104.84128, 1423.8m, 8°
Jan 23, 2020 09:51:52

Photo 10: Wellhead Sign



Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 11: Wellhead Sign



Photo 12: Stained soil removed



Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 13: Wellhead Sign



Photo 14: Wellhead



Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 15: Stained soil