

Inspection Photos
Location Name: SLW RANCH-65N63W /7SWNE
Location #: 327564



Colorado Oil & Gas Conservation Commission
40.41604, -104.47804, 1397.0m, 13°
01/24/2020 01:39:42 PM

Photo #1

SLW Ranch 32-7 (05-123-14865) Wellsite
Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
40.41622, -104.47762, 1402.0m, 291°
01/24/2020 01:48:26 PM

Photo #2

SLW Ranch 32-7, 31-7 Battery site
Inactive | Shut-down
Battery formerly served 1 other well:
(SLW Ranch 22-7)
Plugged & Abandoned | PA