

Inspection Photos

Location Name: SLW RANCH-65N63W /7SENW

Location #: 327565



Photo #1

SLW Ranch 22-7 (05-123-14866) Wellsite

Plugged & Abandoned | PA

~ 45 yds.

Reclamation progressing



Photo #2

SLW Ranch 32-7, 31-7 Battery site

Inactive | Shut-down

Battery formerly served 1 other well:

(SLW Ranch 22-7)

Plugged & Abandoned | PA