

## Inspection Photos

Location Name: SKURICH-65N63W /7NESE

Location #: 331025



**Photo #1**

**Skurich 43-7 (05-123-20044) Wellsite**

**Plugged & Abandoned | PA**

**~ 35 yds.**

*Reclamation progressing*



**Photo #2**

**SLW Ranch 42-7, 41-7, Skurich 43-7 Battery site**

**Abandoned: *ALL Equipment removed***

*Reclamation progressing*