

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RADEL-68S96W /11NWSW

Location ID: 334347



**Photo #0463 from SW corner of location**



**Photo #0464 Multiple holes in tank containment liner.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RADEL-68S96W /11NWSW

Location ID: 334347



Photo #0465 Multiple holes in tank containment liner.



Photo #0466 Multiple holes in tank containment liner.