

## Inspection Photos

Location Name: SLW RANCH-65N63W /7SESE

Location #: 327718



Colorado Oil & Gas Conservation Commission  
40.40794, -104.47293, 1407.0m, 119°  
01/25/2020 12:48:04 PM

### Photo #1

**SLW Ranch 44-7 (05-123-15068) Wellsite**

**Plugged & Abandoned | PA**

*~ 25 yds.*

*Reclamation progressing*



Colorado Oil & Gas Conservation Commission  
40.40817, -104.47702, 1406.0m, 120°  
01/25/2020 12:58:12 PM

### Photo #2

**Skurich/SLW Ranch 7A, SLW Ranch 24-7 Battery site**

**Inactive | Shut-down**

*Battery formerly served 2 other wells:*

*( SLW Ranch 34-7, 44-7 )*

*Plugged & Abandoned | PA*