

Great Western Operating Company LLC, Flessner 14  
121-09259

Inspection #688306834

1/24/2020

Reinspection



**COLORADO**

**Oil & Gas Conservation  
Commission**


Department of Natural Resources



IMPETRO RESOURCES LLC  
FLESSNER 14  
NWNE SEC.30-T1S-R56W  
IN CASE OF EMERGENCY CALL 911

Colorado Oil and Gas Conservation Commission  
39.94176, -103.69306, 4593.2ft, 204°  
01/24/2020 05:02:44 PM



A wide-angle photograph of a flat, open landscape, likely a prairie or tundra. The foreground is covered in dry, brownish vegetation and patches of bare ground. The middle ground shows a continuous expanse of similar vegetation stretching to a flat horizon. The sky is filled with soft, layered clouds, with a warm, orange-yellow glow near the horizon suggesting the time is either dawn or dusk. The overall tone is muted and naturalistic.

Colorado Oil and Gas Conservation Commission  
39.94175, -103.69306, 4596.5ft, 210°  
01/24/2020 05:02:46 PM




Colorado Oil and Gas Conservation Commission

39.94174, -103.69307, 4596.5ft, 189°

01/24/2020 05:02:48 PM



A wide-angle photograph of a flat, open landscape. In the foreground, there is a dirt road or path that appears to be under construction or repair, with visible tire tracks and uneven ground. The road leads towards a flat horizon. In the distance, several utility poles are visible against the sky. The sky is filled with soft, white clouds, and the overall lighting suggests it might be early morning or late afternoon. The ground is covered in dry, yellowish-brown grass or vegetation.

Colorado Oil and Gas Conservation Commission  
39.94176, -103.69308, 4593.2ft, 1°  
01/24/2020 05:02:52 PM