

Inspection Photos

API: 05-043-40025

Operator: JAVERNICK OIL

Inspection Date: 1/23/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40025 | Date: 1/23/2020

Inspection Photos



Photo 1. Facing north toward the location. Vegetation has not fully established. Additional seeding should be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40025 | Date: 1/23/2020

Inspection Photos



Photo 2. There is metal scrap debris and cable that remains at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40025 | Date: 1/23/2020

Inspection Photos



Photo 3. Facing south toward the location. Vegetation has not fully established. Additional seeding should be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40025 | Date: 1/23/2020