

Inspection Photos
Location Name: Runway 23-31H
Location ID: 425509



Photo 1 – Pumping Unit



Photo 2 – Northside of Containment



Inspection Photos
Location Name: Runway 23-31H
Location ID: 425509



Photo 3 – Northwest corner inside Containment



Photo 4 – Southside of Location

Inspection Photos
Location Name: Runway 23-31H
Location ID: 425509



Photo 5 – Southside of Containment




Photo 6 – Unmarked Risers, unused pipe



Inspection Photos
Location Name: Runway 23-31H
Location ID: 425509



Photo 7 – Unmarked Risers



Photo 8 – Unmarked Risers, unused loadline bucket

