

Inspection Photos
Location Name: Duncan 5
Location ID: 313139



Photo 1. Overview of location taken facing northwest.