

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Production facility

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Tank berm on 12/12/2019



Tank berm on 1/27/2020

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Load valves and stained soil on 12/12/2019



Load valves and stained soil on 1/27/2020

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Trash on 12/12/2019



Trash on 1/27/2020

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Unused equipment and trash on 12/12/2019



Unused equipment and trash on 1/27/2020

Inspection Photos
Location Name: Bernhardt 7-16 Tank Battery
Location ID: 448358



Unused equipment on 12/12/2019



Unused equipment on 1/27/2020