

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 15, 2020 12:08:47 PM MST
Server Receive Date:	Jan 15, 2020 12:11:16 PM MST
Reference Number:	20200115-18129650749
Location:	557 Airpark Dr, Durango, CO 81303, USA
	Jan 15, 2020 12:10:41 PM MST [View Map]

Name	colen@horizonenvservices.com
Date	Jan 13, 2020
Well Name	JONES GAS UNIT 1
API Number	50670697700
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

JONES 1
 UP AMERICA PRODUCTION COMPANY
 ELEVATOR SHAFT APR 11 1970 0000
 NAME OF TOWER N/A DATE N/A
 LEGAL N/A CEN N/A
 SURFACE LOCATION NORTH N/A 1000' N 100' W
 LATITUDE 32 50' 00" N LONGITUDE 102 50' 00" W
 LATTITUDE 32 50' 00" N LONGITUDE 102 50' 00" W
 MAP CONTROL CENTER IN THE TOWER N/A
 EMERGENCY CONTACT N/A

location sign

before mowing



Completed work description of corrective action 3
Photo of fourth corrective action completed

after mowing



Completed work description
Completed work description of corrective action 4

removed weeds from around equipment
mowed and removed weeds from around equipment
and in the reclamation area

Additional photos



Additional photos



Completed work description
Summary of all work completed

removed weed debris from location
removed weed debris from around equipment and in
reclamation area