



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Jan 15, 2020 12:18:10 PM MST
Server Receive Date: Jan 15, 2020 12:20:40 PM MST
Reference Number: 20200115-18129651384
Location: 557 Airpark Dr, Durango, CO 81303, USA
Jan 15, 2020 12:19:57 PM MST [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date Jan 13, 2020
Well Name LARSEN GAS UNIT 01-12 1
API Number 50670676700
Select State Colorado
Work type COGCC Inspection AR
Action Complete Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

before mowing

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

after mowing



Completed work description
 Completed work description of corrective action 4
 Additional photos

before mowing
 removed weed debris from around equipment



Additional photos



Additional photos



Additional photos



Additional photos



Completed work description

removed weed debris from around equipment and in
reclamation area

Summary of all work completed

removed weed debris from around equipment and in
reclamation area