



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 15, 2020 12:28:54 PM MST
Server Receive Date:	Jan 15, 2020 12:31:24 PM MST
Reference Number:	20200115-18129652541
Location:	557 Airpark Dr, Durango, CO 81303, USA Jan 15, 2020 12:31:02 PM MST [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Jan 13, 2020
Well Name	LARSEN GAS UNIT 01-12 2
API Number	50670873300
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

removed weed debris from around equipment

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed

removed weed debris from around equipment



Completed work description  
 Completed work description of corrective action 4

removed weed debris from around equipment  
 removed weed debris from around equipment and in  
 reclamation area

Additional photos



Additional photos



Additional photos



Additional photos



Completed work description

Summary of all work completed

removed weed debris from around equipment and in  
reclamation area  
initial treatment 5/29/19