



Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 15, 2020 12:42:16 PM MST
Server Receive Date:	Jan 15, 2020 12:44:45 PM MST
Reference Number:	20200115-18129655235
Location:	557 Airpark Dr, Durango, CO 81303, USA Jan 15, 2020 12:41:40 PM MST [ <a href="#">View Map</a> ]

Information

Name	colen@horizonenvservices.com
Date	Jan 13, 2020
Well Name	MORRIS, JT GAS UNIT A 1
API Number	50670732800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

removed weed debris from around equipment

Photo of third corrective action completed



Completed work description of corrective action 3  
Photo of fourth corrective action completed

removed weed debris from around equipment



Completed work description  
Completed work description of corrective action 4  
Additional photos

removed weed debris from around equipment  
removed weed debris



Additional photos



Completed work description  
Summary of all work completed

removed weed debris from around equipment  
initial treatment 6/20/19