



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Jan 15, 2020 2:19:16 PM MST
Server Receive Date: Jan 15, 2020 2:21:44 PM MST
Reference Number: 20200115-18129669854
Location: 557 Airpark Dr, Durango, CO 81303, USA
Jan 15, 2020 2:21:30 PM MST [[View Map](#)]

Information

Name	colen@horizonenvservices.com
Date	Jan 15, 2020
Well Name	WIRT GAS UNIT B 1A
API Number	50670632800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris Replaced/Repaired Tank Signs

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

before mowing

Photo of third corrective action completed



Completed work description of corrective action 3

after mowing

Photo of fourth corrective action completed



Completed work description

removed old tank sign

Completed work description of corrective action 4

weed debris removal and tank sign removal

Additional photos



Completed work description

initial treatment 6/24/19

Summary of all work completed

addressed inspection findings