



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jan 17, 2020 4:07:02 PM MST
Server Receive Date:	Jan 17, 2020 4:09:30 PM MST
Reference Number:	20200117-18129905574
Location:	557 Airpark Dr, Durango, CO 81303, USA Jan 17, 2020 4:06:42 PM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Jan 16, 2020
Well Name	TAICHERT GAS UNIT 31-01 1
API Number	50670664000
Select State	Colorado
Work type	COGCC Inspection AR

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

frozen sediment and snow cover in bmp

Photo of third corrective action completed



Completed work description of corrective action 3

Photo of fourth corrective action completed



Completed work description

Completed work description of corrective action 4

Summary of all work completed

frozen soil and snow cover in bmp

frozen soil

this site will need to be revisited in spring when soils are not frozen

site needs to be revisited in the spring