

Inspection Photos

Location Name: CORDILLERA 34-7 CA DATE 2-11-20

API#: 05-071-09150

INSP. #: 695102110



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: CORDILLERA 34-7 CA DATE 2-11-20

API#: 05-071-09150

INSP. #: 695102110



PHOTO 3: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 2-11-20.

PHOTO 4: APPEARS THAT FUEL GAS SEPARATOR IS BEING DRAINED ON LOCATION LEAVING AN AREA OF IMPACTED SOIL NEAR COMPRESSOR. CAPTURE AND PROPERLY DISPOSE OF ANY OILY WASTE FROM FUEL GAS SEPARATOR WHEN IT IS DRAINED. PROPERLY DISPOSE OF IMPACTED SOIL CA DATE 2-1-20