



99999999

WELL SITE INSPECTION FORM

not on computer

WELL NAME Hruza #1API NUMBER 05 - 075 - 8137OPERATOR Hibbert

PERMIT NUMBER _____

LOCATION SESE 33-12N-53WCOUNTY LoperFIELD WCINSPECTOR SPAL/PA/DA DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) ✓ FAIL(N) _____ DATE 1/26/89 FN _____ FD _____ WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____

CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____

RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES ✓ NO _____ PITS BACKFILLED: YES ✓ NO _____MATERIAL BURIED: YES ✓ NO _____ NA _____ SITE CLEAN: YES ✓ NO _____BOND RELEASE OK: YES ✓ NO _____ FED _____ HOLE MARKER: YES _____ NO ✓

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS ✓ old pits 1/2 worn away - cow pasture

00300612